

TOTAL PERFORMANCE VAN'S AIRCRAFT

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 14-10-15

Date Released: Oct 15, 2014
Date Effective: Oct 15, 2014
Subject: SkyView Dual EFIS Screen
Affected Models: RV-12
Required Action: Install co-pilot SkyView EFIS screen.
Time of Compliance: N/A
Supercedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 3.0 Hours / None

Level of Certification: Owner: LSA Repairman Inspection
SLSA: LSA Repairman Maintenance, A&P

Synopsis:

This notification allows the installation of a second co-pilot EFIS screen.

Method of Compliance:

Step 1: Install a second EFIS screen on the co-pilot side of the aircraft in accordance with KAI Section 43B.

Step 2: Update aircraft Weight and Balance data in accordance with KAI Section 43B.

Step 3: Make a logbook entry indicating compliance with Notification 14-10-15.

Step 4: Place a copy of this notification in the back of the maintenance manual for your aircraft.

Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

PART NUMBER

Qty	Item
19	AN426AD3-4
2	ES-00207
1	F-00011
1	F-00024
1	F-00029-R
1	F-1200 (note "F-1200" is for an ELSA, for an SLSA order "F-1200 SLSA")
1	F-12123B
1	F-12175
6	K1000-06
14	LP4-3
1	IF DYNON D1000T/A-VA

2	MS35206-215
2	MS21044N04
6	PLASTIC TIE-WRAP 4"
1	WH-00054
1	WH-00106