



SAFETY DIRECTIVE 00107

Date Released: Dec 24, 2024

Date Effective: Dec 24, 2024

Subject: Notification of Rotax SB-912 i-016 / SB-915 i-016
SB-916 i-006: Inspection and/or Replacement of oil spray
nozzle for ROTAX Aircraft Engines

Affected Models: RV-12iS using a Rotax 912iS Sport Engine

Refer to Rotax SB-912 i-016 / SB-915 i-016
SB-916 i-006 for a list of affected engine serial numbers

Required Action: Mandatory completion of Rotax SB-912 i-016 / SB-915 i-
016

Time of Compliance: See Rotax SB-912 i-016 / SB-915 i-016

Supersedes Notice:

Labor Required / SLSA Warranty Allowance: SB-912 i-016 / SB-915 i-016

Level of Certification: See Rotax SB-912 i-016 / SB-915 i-016

Synopsis:

To ensure all customers are aware of potential oil spray blockage Van's Aircraft is publishing this Safety Directive for the notification of Rotax SB-912 i-016 / SB-915 i-016.

Materials Required:

Refer to Rotax SB-912 i-016 / SB-915 i-016.

Method of Compliance:

Step 1: Complete Rotax SB-912 i-016 / SB-915 i-016.

Step 2: Make a logbook entry indicating compliance with service document per the requirements of the controlling authority/agency.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>