

NOTE: Parts vary due to manufacturing tolerances. In Detail B make certain bolt grip length is correct. If gap exists after using maximum number of washers, tighten nut and bolt to eliminate gap.

WARNING: Do not exceed the maximum number of washers shown in Detail B.

