

TOTAL PERFORMANCE
VAN'S AIRCRAFT

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com
Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 16-07-14

Date Released: July 14, 2016
Date Effective: July 14, 2016
Subject: Passenger Warning Placard
Affected Models: All flying RV-12 aircraft and Documentation kits shipped prior to July 14, 2016.
Required Action: Upgrade Passenger Warning Placard to current version
Time of Compliance: N/A
Supersedes Notice: None

Labor Required / SLSA Warranty Allowance: .25 Hours / None

Level of Certification: ELSA and SLSA - Owner

Synopsis:

Previous Passenger Warning Placard omitted text required for LSA compliance. Notification provides source and instruction for installation of revised placard.

Parts shipped on or after July 14, 2016 are not affected by this notification.

Method of Compliance:

Step 1: Obtain revised placard for your aircraft. See Part No. and illustrations below.

Step 2: Remove existing passenger warning placard if applicable.

Step 3: Clean area where revised placard will be installed.

Step 4: Install revised placard.

Place a copy of this notification in the back of your aircraft's maintenance manual (MM). Record the addition of this notification at the bottom of the MM table of contents.

PART NUMBER

Revised placards for all RV-12 Documentation Kits shipped prior to July 14, 2016.

<u>Qty</u>	<u>Part No.</u>	<u>Description</u>
1.000	F-1200PW	ELSA PASSENGER WARNING PLACARD
1.000	F-1200SLSAPW	SLSA PASSENGER WARNING PLACARD



Part No.: F-1200PW



Part No.: F-1200SLSAPW